



**Department of Energy**  
Western Area Power Administration  
Desert Southwest Customer Service Region  
P.O. Box 6457  
Phoenix, AZ 85005-6457

JAN 14 2008

Dear Western Area Power Administration Customer:

Western Area Power Administration (Western) is evaluating the potential of consolidating three of its Balancing Authorities; the Rocky Mountain Region, Upper Great Plains (West), and the Desert Southwest Region, into a single Balancing Authority.

Western is committed to timely and meaningful communication with customers during the study process. As we move forward, you will have opportunities to be involved in the process, including briefings and group discussions at key points. Western will host pre-decisional information meetings to discuss this potential consolidation with our interested customers on February 12, 2008, 1:00 p.m. in Western's Desert Southwest Region office located at 615 South 43<sup>rd</sup> Avenue, Phoenix, Arizona, and on February 14, 2008, at 10:00 a.m. at the Ranch at the Larimer County Fairgrounds in Loveland, Colorado.

For those customers attending the Phoenix Meeting, access to Western facilities is controlled. Any U.S. citizen wishing to attend must present an official form of picture identification, such as a U.S. driver's license, U.S. passport, U.S. Government ID, or U.S. Military ID, at the time of the meeting. Foreign nationals should contact W. Troy Stine, 602-605-2792 or [stine@wapa.gov](mailto:stine@wapa.gov), immediately to obtain the necessary form for admittance to Western. Also, please RSVP to (602) 605-2792, if you will be attending the Phoenix meeting.

For those customers attending the Loveland meeting, please enter the Larimer County Conference Center, First National Bank Building at the Larimer County Fairgrounds (see enclosed maps). Please RSVP to (970) 461-7382, if you will be attending the Loveland meeting.

For additional information or if you have questions, please telephone me at (602) 605-2453.

Sincerely,

A handwritten signature in black ink, appearing to read "J. Tyler Carlson", is written over the typed name.

J. Tyler Carlson  
Regional Manager



**Department of Energy**  
Western Area Power Administration  
Rocky Mountain Customer Service Region  
P.O. Box 3700  
Loveland, CO 80539-3003

JAN 14 2008

Dear Western Area Power Administration Customer:

Western Area Power Administration (Western) is evaluating the potential of consolidating three of its Balancing Authorities; the Rocky Mountain Region, Upper Great Plains Region (West), and the Desert Southwest Region, into a single Balancing Authority.

Western is committed to timely and meaningful communication with customers during the study process. As we move forward, you will have opportunities to be involved in the process, including briefings and group discussions at key points. Western will host pre-decisional information meetings to discuss this potential consolidation with our interested customers on February 12, 2008, 1:00 p.m. in Western's Desert Southwest Region office located at 615 South 43<sup>rd</sup> Avenue, Phoenix, Arizona, and on February 14, 2008, at 10:00 a.m. at the Ranch at the Larimer County Fairgrounds in Loveland, Colorado.

For those customers attending the Phoenix meeting, access to Western facilities is controlled. Any U.S. citizen wishing to attend must present an official form of picture identification, such as a U.S. driver's license, U.S. passport, U.S. Government ID, or U.S. Military ID, at the time of the meeting. Foreign nationals should contact W. Troy Stine, (602) 605-2792 or [stine@wapa.gov](mailto:stine@wapa.gov), immediately to obtain the necessary form for admittance to Western. Also, please RSVP to (602) 605-2792, if you will be attending the Phoenix meeting.

For those customers attending the Loveland meeting, please enter the Larimer County Conference Center, First National Bank Building, at the Larimer County Fairgrounds (see enclosed maps). Please RSVP to (970) 461-7382, if you will be attending the Loveland meeting.


For additional information or if you have questions, please telephone me at (970) 461-7201.

Sincerely,

A large, stylized handwritten signature in black ink, appearing to read "James D. Keselburg".

James D. Keselburg  
Regional Manager

2 Enclosures




MAPQUEST

© 2007 MapQuest Inc.

Map Data © 2007 N/A

I-25 Frontage Road



Fairgrounds Avenue

County Road 5

**JAN 16 2008**

Dear Customers:

Western Area Power Administration (Western) is evaluating the potential of consolidating three of its Balancing Authorities; the Upper Great Plains Region West Side Balancing Authority (formerly known as the Upper Great Plains Region West Side Control Area), the Rocky Mountain Region, and the Desert Southwest Region, into a single Balancing Authority.

Western is committed to timely and meaningful communication with customers during the study process. As we move forward, you will have opportunities to be involved in the process, including briefings and group discussions at key points. Western will host pre-decisional information meetings to discuss this potential consolidation with our interested customers on **February 12, 2008, 1:00 p.m.** in Western's Desert Southwest Region office located at 615 South 43<sup>rd</sup> Avenue, Phoenix, Arizona, and on **February 14, 2008, at 10:00 a.m.** at the Ranch at the Larimer County Fairgrounds in Loveland, Colorado.

For those customers attending the Phoenix meeting, access to Western facilities is controlled. Any U.S. citizen wishing to attend must present an official form of picture identification, such as a U.S. driver's license, U.S. passport, U.S. Government ID, or U.S. Military ID, at the time of the meeting. Foreign nationals should contact Mr. W. Troy Stine at (602) 605-2792 or [stine@wapa.gov](mailto:stine@wapa.gov) immediately to obtain the necessary form for admittance to Western. Also, please RSVP to (602) 605-2792, if you will be attending the Phoenix meeting.

For those customers attending the Loveland meeting, please enter the Larimer County Conference Center, First National Bank Building, at the Larimer County Fairgrounds (see enclosed maps). Please RSVP to (970) 461-7382, if you will be attending the Loveland meeting.

For additional information or if you have questions, please telephone me at (406) 247-7405.

Sincerely,

**Robert J. Harris**

Robert J. Harris  
Regional Manager

Enclosures

B6202.BL;jap;cdj'01/16/08;R:\Groups\Contracts\Letters to Customers\Pankratz\UGPR  
Customer Briefing invitation Ltr.doc



**Department of Energy**  
**Western Area Power Administration**  
**Sierra Nevada Customer Service Region**  
**114 Parkshore Drive**  
**Folsom, California 95630-4710**

JAN 16 2008

Dear Central Valley Project Customers:

The Western Area Power Administration (Western) is evaluating the potential of consolidating three of its Balancing Authorities; the Rocky Mountain Region, Upper Great Plains Region (West), and the Desert Southwest Region into a single Balancing Authority.

Western is committed to timely and meaningful communication with customers during the study process. As we move forward, you will have opportunities to be involved in the process, including briefings and group discussions at key points. Western will host pre-decisional information meetings to discuss this potential consolidation with our interested customers on February 12, 2008, at 1 p.m. in Western's Desert Southwest Regional office located at 615 South 43<sup>rd</sup> Avenue, Phoenix, Arizona, and on February 14, 2008, at 10 a.m. at the Ranch at the Larimer County Fairgrounds in Loveland, Colorado.

For those customers attending the Phoenix meeting, access to Western facilities is controlled. Any U.S. citizen wishing to attend must present an official form of picture identification, such as a U.S. driver's license, U.S. passport, U.S. Government ID, or U.S. Military ID, at the time of the meeting. Foreign nationals should contact W. Troy Stine, 602-605-2792, or [stine@wapa.gov](mailto:stine@wapa.gov), immediately to obtain the necessary form for admittance to Western. If you plan on attending the Phoenix meeting, please call the number mentioned above.

For those customers attending the Loveland meeting, please enter the Larimer County Conference Center, First National Bank Building at the Larimer County Fairgrounds (see enclosed maps). If you plan to attend the Loveland meeting, please call (970) 461-7382.


For additional information or if you have questions, please telephone me at (916) 353-4418.

Sincerely,

A large, stylized handwritten signature in black ink, appearing to read "T. Boyko".

Thomas R. Boyko  
Regional Manager

2 Enclosures



MAPQUEST ST.

7

7

26

Western Area  
Power  
Admin.

Byrd Dr

E Crossroad 1 SW

Nw Frontage Rd

E Frontage Rd

25

250

26

Cydesdale Pkwy

The Ranch

St Cloud Dr

Fairground Ave

E Cross


© 2007 MapQuest Inc.

Map Data © 2007 NPS



Calf Stream Ct

I-25 Frontage Road



Fairgrounds Avenue

County Road 5





**Department of Energy**  
Western Area Power Administration  
150 East Social Hall Avenue, Suite 300  
Salt Lake City, UT 84111-1580

JAN 15 2008

Dear Customer:

Western Area Power Administration (Western) is evaluating the potential to consolidate three of its Balancing Authorities (the Rocky Mountain Region, the Upper Great Plains Region (West), and the Desert Southwest Region) into a single Balancing Authority.

Western is committed to timely and meaningful communication with its customers during this study process. As we move forward, you will have opportunities to be involved in the process including briefings and group discussions at key points. Western will host pre-decisional informational meetings to discuss this potential consolidation with our interested customers on February 12, 1 p.m., in Western's Desert Southwest Region office located at 615 South 43<sup>rd</sup> Avenue, Phoenix, Arizona, and on February 14, 10 a.m., at the Ranch at the Larimer County Fairgrounds in Loveland, Colorado.

For those customers attending the Phoenix meeting, access to Western facilities is controlled. Any U.S. citizen wanting to attend must present an official form of picture identification, such as a U.S. driver's license, U.S. passport, U.S. Government ID, or U.S. Military ID, for clearance. Foreign nationals should contact W. Troy Stine, (602) 605-2792 or [stine@wapa.gov](mailto:stine@wapa.gov), **immediately** to obtain the necessary form for admittance to Western. Also, please telephone (602) 605-2792 if you will be attending the Phoenix meeting.

For those customers attending the Loveland meeting, once inside the Ranch at the Fairgrounds, please enter the Larimer County Conference Center, First National Bank Building (see enclosed maps). Please telephone (970) 461-7382 if you are attending the Loveland meeting.

For additional information or if you have any questions, please telephone me at (801) 524-6372.

Sincerely,

**Bradley S. Warren**

Bradley S. Warren  
CRSP Manager

Enclosures